INSPECTION REPORT



For the Property at:

8313 ARMETALE LANE

FAIRFAX STATION, VA 22039

Prepared for: JOHN DOE

Inspection Date: Tuesday, June 7, 2022

Prepared by: Steve Friday



Consumer Resources 8313 Armetale Lane Fairfax Station, VA 22039 703-309-8200

www.crhomeinspection.com stevefriday@cox.net



INVOICE

August 4, 2022

Client: John Doe

Report No. 1001 For inspection at: 8313 Armetale Lane Fairfax Station, VA 22039 on: Tuesday, June 7, 2022

Home inspection \$400.00

> Total \$400.00

8313 Armetale Lane, Fairfax Station, VA June 7, 2022

www.crhomeinspection.com

SUMMARY

ROOFING

EXTERIOR

STRUCTURE ELECT

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

Note: For the purpose of this report the building is considered to be facing **North**.

This Summary outlines potentially significant issues from a cost or safety standpoint. This section is provided as a courtesy and cannot be considered a substitute for reading the entire report. Please read the complete document.

Priority Maintenance Items

This concludes the Summary section.

The remainder of the report describes each of the home's systems and also details any recommendations we have for improvements. Limitations that restricted our inspection are included as well.

The suggested time frames for completing recommendations are based on the limited information available during a pre-purchase home inspection. These may have to be adjusted based on the findings of specialists.

Home Improvement - ballpark costs

8313 Armetale Lane, Fairfax Station, VA June 7, 2022

SUMMARY

STRUCTURE PLUMBING ROOFING

Description


Roofing material: • Asphalt shingles

Flashing material:

Metal







www.crhomeinspection.com

2. Metal



3. Metal

8313 Armetale Lane, Fairfax Station, VA June 7, 2022 www.crhomeinspection.com EXTERIOR STRUCTURE ELECTRICAL SUMMARY INSULATION PLUMBING ROOFING Inspection Methods and Limitations Inspection performed: • By walking on roof

EXTERIOR

Report No. 1001

8313 Armetale Lane, Fairfax Station, VA www.crhomeinspection.com June 7, 2022 SUMMARY INSULATION PLUMBING EXTERIOR

Description

Wall surfaces and trim: • Vinyl siding

8313 Armetale Lane, Fairfax Station, VA June 7, 2022

www.crhomein spection.com

SUMMARY

ROOFING

XTERIOR

STRUCTURE ELECTR

HEATI

COOLING

NSULATIO

PLUMBING

INTERIOF

Description

Configuration: • Basement • Crawlspace **Foundation material:** • Poured concrete

Floor construction: • Joists

Exterior wall construction: • Wood frame

Roof and ceiling framing: • Trusses • Oriented Strand Board (OSB) sheathing

Inspection Methods and Limitations

Inspection limited/prevented by: • Carpet/furnishings • Storage

Attic/roof space: • Inspected from access hatch
Crawlspace: • Entered but access was limited

8313 Armetale Lane, Fairfax Station, VA June 7, 2022

www.crhomeinspection.com

SUMMARY

ROOFING

STRUCTU

ELECTRIC

HEATIN

COOLIN

INSULATION

PLUMBING

INTERIOR

Description

Service size: • 100 Amps (240 Volts)

Main disconnect/service box type and location: • Breakers - basement

Distribution wire (conductor) material and type: • Copper - non-metallic sheathed

Smoke alarms (detectors): • Present

Carbon monoxide (CO) alarms (detectors): • Present

HEATING

Report No. 1001

8313 Armetale Lane, Fairfax Station, VA June 7, 2022 SUMMARY

www.crhomeinspection.com

ROOFING

HEATING

Description

Heating system type: • Furnace

Approximate capacity: • 100,000 BTU/hr

Approximate age: • 5 years

Fireplace/stove: • Wood-burning fireplace

Location of the thermostat for the heating system: • Living Room

COOLING & HEAT PUMP

Report No. 1001

8313 Armetale Lane, Fairfax Station, VA June 7, 2022

www.crhomeinspection.com

SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR

Description

Air conditioning type: • Air cooled • Central

Cooling capacity: • 36,000 BTU/hr

Compressor approximate age: • 10 years

Location of the thermostat for the cooling system: • Living Room

INSULATION AND VENTILATION

Report No. 1001

www.crhomeinspection.com

8313 Armetale Lane, Fairfax Station, VA June 7, 2022 SUMMARY ROOFING INSULATION

Description

Attic/roof insulation material: • Cellulose Attic/roof insulation amount/value: • R-40

Attic/roof air/vapor barrier: • Plastic Wall insulation material: • Not visible

Floor above basement/crawlspace insulation material: • Glass fiber Floor above basement/crawlspace insulation amount/value: • R-20

Floor above basement/crawlspace air/vapor barrier: • Plastic

Inspection Methods and Limitations

Attic inspection performed: • From access hatch

PLUMBING

Report No. 1001

8313 Armetale Lane, Fairfax Station, VA June 7, 2022 www.crhomeinspection.com

SUMMARY

ROOFING

PLUMBING

Description

Water supply source (based on observed evidence): • Public

Supply piping in building: • Copper

Main water shut off valve at the: • Front of the basement

Water heater type: • Tank

Water heater fuel/energy source: • Gas Water heater tank capacity: • 40 gallons Waste and vent piping in building: • Plastic

Main gas shut off valve location: • Exterior • Gas meter

8313 Armetale Lane, Fairfax Station, VA June 7, 2022

www.crhomeinspection.com

SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR

Inspection Methods and Limitations

Inspection limited/prevented by: • Carpet • Storage/furnishings

END OF REPORT